

IPCC : The Edible oil Refining Co. Ltd.

B013 (2.7)
Risk Assessments

- (a) 2.7(a) Risk Assessment Sheet (attached)
- (b) We confirm that the recommendations listed in the four documents (fire and safety audit 2003; OHS report 2004; Legal compliance report 2003 and Insurance report 2008 have been implemented.
- (c) 2.7(c) detailed fire Plan will be forwarded next week.
- (d) Oil tanks are bunded. If and when spills occur, if minor spills occur these are neutralized and converted to sodium soap (common soap) with caustic soda.

Fuel tanks for boilers are also bunded and if any minor spills outside the bunded perimeter may occur this is sprinkled with gravel and disposed of through our waste collector.

In the many years of operation we have never experienced anything above 2/3 litres of fuel oil spills.

