

C.J.C. CAMILLERI Bros Co Ltd

Nigret Quarry

Triq Wied Ganu

Zurrieq

Compay Number: C5557

VAT Number: 1249 – 9106

Dust Mitigation Measures

CJC Camilleri Bros Co Ltd endeavour to safeguard the environment against excessive dust in the air. The Company has always taken the following measures:

- Maintaining low stockpile heights – the management of the quarry has a policy to keep the stockpile at the lowest minimum of five working days supply of crashed spalls and sand. Once this level of stock is reached, the crashed material is loaded and transported to the company's client's plants.
- Limiting dust emissions – quarried rocks are transported to the crusher area where the rocks are 'fed' into a feeder which are wet before these are crushed. Afterward, the crushed material find the way into separate storage rooms, which are situated in the quarry. The crushed material is transported to the relevant stock pile in the quarry. In this way, since the rocks are wet the resulting crushed material has low dust levels.
- Working at low levels – the quarry is situated in a downhill area and work are carried out at low levels.
- Currently the crusher is not being operated due to the back-filling, however once the crushers will be operated, sprinklers will be installed in order to minimize the dust produced during crushing.
- Scarified material is kept in a designated area in the quarry (as marked on the attached site plan). As with other material these are kept in low stock-piles and below street level.
- Scarified material stock pile, when available will be periodically wetted in order to reduce dust emissions.

Telephone Number: 21640192

Email Address:

cjccamilleriquarry@gmail.com

C.J.C. CAMILLERI Bros Co Ltd

Nigret Quarry

Triq Wied Ganu


Zurrieq

Compay Number: C5557

VAT Number: 1249 – 9106

- The quarry site is distant from the residential area and is confined in the quarry area.
- Power-wash equipment – a water reservoir was installed at the entrance/exit of the quarry site so that before, during and after operations or as necessary, water is left flowing down the passage leading to the quarry, to remove any accumulated dust. This ensures that trucks leaving the quarry do not carry dust onto public roads.
- The road leading to the quarry has recently been asphalted by the Zurrieq Local Council.
- Frequently, especially in summer, we engage a contractor who has a water bowser equipped with sprinkling capabilities to wet all the roads within the quarry area (refer to attached photos)
- Two wheeled power-washers are kept on site to be used as necessary

The Company tries to ensure that these mitigation measures are adhered to.



Philip Camilleri
Manager Operations

Telephone Number: 21640192

*Email Address:
cjccamilleriquarry@gmail.com*