

BUND WALL TEST CERTIFICATE

Test Certificate No. 19-609-04

Place: Delimara Power Station
Triq il-Power Station, Marsaxlokk, Malta.

Location: Delimara 4 – Ammonia Dosing Skid Tank

Description: Stainless Steel Tank – Thickness 1mm
Overall Dimensions: 1750 x 1050 x 300mm
Capacity: Approx. 0.55m³

Bund Lining Material: None

System Volume to be retained: Approx. 500 litres

Methodology: Day 1: 5th December 2019 at 09.30hrs
Bund filled with Water and level of water noted to be 238mm
Water allowed to settle for 24 hrs.

Day 2: 6th December 2019 at 09.30hrs
Level of Water in Bund Wall Noted to be 238mm

Result: Bund Wall Holds - Satisfactory



Water level at Start: 238mm



Water level after 24hrs: 238mm

Ing. Lawrence Dimech

Date: 6th December 2019