

**Ing. Martin Gauci**

B.Mech.Eng. (Hons.)  
Engineering Consultant

Residence: 58, Thira', Mintba Str., Marsascala  
VAT Reg. No. 1784-3108

Tel. +356 9110075

---

**Record of examination and test of plant and equipment**

**Ref.: MG/RP/09162**

**Equipment:** Glycol pit being safety containment in case of leakages on main glycol tank at Delimara power station

**Name and address of owner:** Reganosa Malta Ltd

**Description of Equipment:** The pit is approximately 13m x 14m area, with a 200mm concrete wall ready to take any spills or leakages, if any occur.

**Testing :** The pit was filled with water to an adequate level for this test.  
Water level measured on the 28<sup>th</sup> November 2019 = 50mm  
Water level measured on 29<sup>th</sup> November 2019 = 49mm

Recorded ambient temperature = 19C

**Declaration:** This is to certify that on 29<sup>th</sup> November 2019, I have inspected the pit described in this record, and found it to be maintained in a satisfactory condition to hold water satisfactorily without any leaks.  
Pit must be re-tested within 1 year.

**Name and address of person making declaration:**

**Ing. Martin Gauci**  
**B.Mech. Eng.(Hons)**

**Engineering Warrant No.:**

**Address:**

**Tel. No.:**

**762**

**58,Thira',Mintba Str.,  
Marsascala.**

**99110075**



ING M. GAUCI  
B MECH ENG(HONS)

**Ref.: MG/RP/09162**

**Signature:**

**26<sup>th</sup> November 2019**