

Ing. Martin Gauci

B.Mech.Eng. (Hons.)
Engineering Consultant

Residence: 58, Thira', Mintba Str., Marsascala
VAT Reg. No. 1784-3108

Tel. +356 9110075

**Record of examination and test of plant and
equipment**

Ref.: MG/RP/09163

Equipment: Transformer pit being safety containment in case of leakages on transformer tank at Delimara power station Label: 12BFT20

Name and address of owner: Reganosa Malta Ltd

Description of Equipment: The pit is a containment tank under transformer, ready to take any spills or leakages, if any occur.

Testing : The pit was filled with water to an adequate level for this test.
Water level measured on the 26th November 2019 = 495mm below grid
Water level measured on 27th November 2019 = 500mm

Recorded ambient temperature = 19C

Declaration: This is to certify that on 27th November 2019, I have inspected the pit described in this record, and found it to be maintained in a satisfactory condition to hold water satisfactorily without any leaks.
Pit must be re-tested within 1 year.

Name and address of person making declaration:

Ing. Martin Gauci
B.Mech. Eng.(Hons)
Engineering Warrant No.: 762
Address: 58,Thira',Mintba Str.,
Marsascala.
Tel. No.: 99110075



ING M. GAUCI
B MECH ENG (HONS)

Ref.: MG/RP/09163

Signature:

28th November 2019