

Ing. Martin Gauci

B.Mech.Eng. (Hons.)
Engineering Consultant

Residence: 58, Thira', Mintba Str., Marsascala
VAT Reg. No. 1784-3108

Tel. +356 9110075

**Record of examination and test of plant and
equipment**

Ref.: MG/RP/09165

Equipment: Transformer pit being safety containment in case of leakages on one transformer tank at Delimara power station Label: 12BFT30

Name and address of owner: Reganosa Malta Ltd

Description of Equipment: The pit is a containment tank under transformer, ready to take any spills or leakages of cooling liquids, if any occur.

Testing : The pit was filled with water to an adequate level for this test.
Water level measured on the 18th December 2019 = 580mm below grid
Water level measured on 19th December 2019 = 585mm below grid.

Recorded ambient temperature = 19C

Declaration: This is to certify that on 19th December 2019, I have inspected the pit described in this record, and found it to be maintained in a satisfactory condition to hold water satisfactorily without any leaks.
Pit must be re-tested within 1 year.

Name and address of person making declaration:

Ing. Martin Gauci
B.Mech. Eng.(Hons)

Engineering Warrant No.:

Address:

Tel. No.:

762

**58,Thira',Mintba Str.,
Marsascala.**

99110075



**ING M.GAUCI
B MECH ENG(HONS)**

Ref.: MG/RP/09165

Signature:

19th December 2019